The Home Shop Machinist

2001 Volume Nineteen Index

January/February – J/F
March/April – M/A
May/June – M/J
July/August – J/A
September/October – S/O
November/December – N/D

A

ACKER, STEVE
- Book Review
  - Iron Melting Cupola Furnaces J/F 18
- Machining a Cast Iron Faceplate J/A 54

Additions and Modifications to the Sakai ML-360 Lathe J/F 26
Another Edge Finder J/F 50
Angle Makes All the Difference N/D 18
Angle Measurement with an Adjustable Square J/A 61
Atlas Mill Update, An
- Part 1 J/A 16
- Part 2 S/O 66
- Part 3 N/D 64

B

Balanced Knurling Tool, A
- Part 1 J/F 58
- Part 2 M/A 56
- Part 3 M/J 56

BOOK REVIEWS
- Iron Melting Cupola Furnaces J/F 18
- Machinist's Ready Reference, 9th Edition J/A 13

BOCHERT. JOHN
- Larger Spherical Radii J/A 62

BUTTERICK, RICHARD
- Tapping Machine
  - Part 1 M/A 22
  - Part 2 M/J 28
  - Part 3 J/A 32

C

Casting Iron in the Home Foundry J/A 22
CHASTAIN, STEPHEN
- Casting Iron in the Home Foundry J/A 22

Chips & Sparks
- 20-20 Hindsight J/A 71
- Cutting Square Threads J/A 70
- Dividing Head Disc Chart M/A 16
- Drawbar Secret S/O 76
- Edge Finders J/A 70
- Expanding Mandrel M/A 16
- Holding Thin Metal J/A 69
- Making Parallels Work J/A 69
- No More Clutter N/D 16
- Pain Reliever, A J/A 71
- Regrinding Live Centers N/D 16
- Still Holding S/O 76
- Tailstock Tale J/F 16
- Toolholder Advantage J/F 16
- Unstuck Chuck, The J/A 69
- Upright Nail Set S/O 77
- Winning Exercise, A M/A 16

CHRISTIANSEN, GARY
- Setting Up Fly-cutter Bits S/O 64
- Clamp Set for Your Mill J/F 61

COLLINS, MARSHAL
- Chips & Sparks
  - Dividing Head Disc Chart M/A 16
  - Drawbar Secret S/O 76
  - Tailstock Tale J/F 16
  - Upright Nail Set S/O 77
- Overhaul of the "Old Lady" J/A 60
- Replacing Quill Bearings N/D 52

Computers in the Shop
- (see FRIESTAD, ROLAND)

COURTS, RANDALL
- Chips & Sparks
  - No More Clutter N/D 16

D

DAMERELL, MARSHALL
- Chips & Sparks
  - Making Parallels Work J/A 69

Digital Readout for the Grizzly G-1005 Mill-Drill
- Part 1 S/O 52
- Part 2 N/D 58

DuBOIS, ALTON A.
- Chips & Sparks
  - Pain Reliever, A J/A 71

E

EASTWOOD, NORMAN
- Phoenix Horizontal Milling and Boring Machine, The
  - Part 1 J/F 20
  - Part 2 M/A 32
  - Part 3 M/J 36
  - Part 4 J/A 47
  - Part 5 S/O 42

Easy Lathe Collet Adapter, An N/D 61
ELECTRONICS
- Computers in the Shop
  - (see FRIESTAD, ROLAND)
- Digital Readout for the Grizzly G-1005 Mill-Drill
  - Part 1 S/O 52
  - Part 2 N/D 58
- How Many Turns? How Many Holes? J/F 56

F

FOSTER, JOHN
- Chips & Sparks
  - Cutting Square Threads J/A 70

Free Pendulum Clock
- Part 1 J/F 40
- Part 2 M/A 42
- Part 3 M/J 46

FRIESTAD, ROLAND
- Computers in the Shop
  - Digital Readout for the Grizzly G-1005 Mill-Drill
    - Part 1 S/O 52
    - Part 2 N/D 58

From the Editor
- (see KNOPF, NEIL)
- (see RICE, JOE)

G

GINGRICH, MARTIN
- Overhauling a Jacobs Chuck N/D 55

Guest Editorial
- (see SLAUSON, MATHEW)

H

HANSON, WAYNE
- Poor Man's T-Slot Rotary Table
  - Part 1 J/F 32
  - Part 2 M/A 50
- Tilt Body Indexer
  - Part 1 M/J 18
  - Part 2 J/A 38
  - Part 3 S/O 34
  - Part 4 N/D 38

HOFFMAN, EDWARD G.
- Jigs & Fixtures
  - Selecting Mechanical Fasteners
    - Part 4 J/F 62
    - Part 5 M/A 60
    - Part 6 M/J 60
  - Lifting Devices
    - Part 1 J/A 66
    - Part 2 S/O 70
    - Part 3 N/D 67

HOLM, PAUL
- Angle Makes All the Difference N/D 18

How Many Turns? How Many Holes? J/F 56

I

Induction Motors and Rotary Phase Converters N/D 26

J

Jigs & Fixtures
- (see HOFFMAN, EDWARD G.)

JOYNT, TOM
- Chips & Sparks
  - Winning Exercise, A M/A 16

K

KNOPF, NEIL
- From the Editor S/O 6, N/D 6

KOIZUMI, EDWARD S.
- Chips & Sparks
  - 20-20 Hindsight J/A 71

KOUHOUPT, RUDY
- Micro Machinist, The
  - Atlas Mill Update
    - Part 1 J/A 16
    - Part 2 S/O 66
    - Part 3 N/D 64
  - Balanced Knurling Tool, A
    - Part 1 J/F 58
    - Part 2 M/A 56
    - Part 3 M/J 56

KRAUT, BRIAN
- Product Review
  - Precision Brand Tool Black M/A 18

L

LAIL, HAROLD A.
- Chips & Sparks
  - Holding Thin Metal J/A 69

LANG, ROGER
- Additions and Modifications to the Sakai ML-360 Lathe J/F 26

LATHE ACCESSORIES
- Additions and Modifications to the Sakai ML-360 Lathe J/F 26
- Balanced Knurling Tool, A
  - Part 1 J/F 58
  - Part 2 M/A 56
  - Part 3 M/J 56
- Easy Lathe Collet Adapter, An N/D 61
- Machining a Cast Iron Faceplate J/A 54
- Overhaul of the "Old Lady" J/A 60
- Scroll Chucks - Their Care and Repair S/O 58

Larger Spherical Radii J/A 62

Lifting Devices
(see HOFFMAN, EDWARD G.)

Locating Stop for the Milling Vise, A S/O 62

M

Machining a Cast Iron Faceplate J/A 54

MAIER, JEFFREY C.
- Free Pendulum Clock
  - Part 1 J/F 40
  - Part 2 M/A 42
  - Part 3 M/J 46
- Tesla Turbine
  - Part 1 S/O 18
  - Part 2 N/D 43

MacMANUS, DAVID
- Chips & Sparks
  - Still Holding S/O 76

McFARLANE, ALAN
- Chips & Sparks
  - Toolholder Advantage J/F 16

McKEE, JIM
- Modified Base for a Band Saw, A J/A 64

McKNIGHT, JIM
- Easy Lathe Collet Adapter, An N/D 61

Micro Machinist, The
(see KOUHOUPT, RUDY)

MILLER, NATHAN
- Scroll Chucks – Their Care and Repair S/O 58

MILLING MACHINE ACCESSORIES
- Another Edge Finder J/F 50
- Atlas Mill Update
  - Part 1 J/A 16
  - Part 2 S/O 66
  - Part 3 N/D 64
- Clamp Set for Your Mill J/F 61
- Digital Readout for the Grizzly G-1005 Mill-Drill
  - Part 1 S/O 52
  - Part 2 N/D 58
- Larger Spherical Radii J/A 62
- Locating Stop for the Milling Vise, A S/O 62
- Phoenix Horizontal Milling and Boring Machine, The
  - Part 1 J/F 20
  - Part 2 M/A 32
  - Part 3 M/J 36
  - Part 4 J/A 47
  - Part 5 S/O 42
- Poor Man's T-Slot Rotary Table
  - Part 1 J/F 32
  - Part 2 M/A 50
- Replacing Quill Bearings N/D 52
- Setting Up Fly-cutter Bits S/O 64
- Tilt Body Indexer
  - Part 1 M/J 18
  - Part 2 J/A 38
  - Part 3 S/O 34
  - Part 4 N/D 38

Modified Base for a Band Saw, A J/A 64

O

Overhaul of the "Old Lady" J/A 60

Overhauling a Jacobs Chuck N/D 55

P

PETERS, GERALD
- Chips & Sparks
  - Regrinding Live Centers N/D 16

PETERSEN, BIRK
- Tale of Three Smoke-poles N/D 57

Phoenix Horizontal Milling and Boring Machine, The
- Part 1 J/F 20
- Part 2 M/A 32
- Part 3 M/J 36
- Part 4 J/A 47
- Part 5 S/O 42

Poor Man's T-Slot Rotary Table
- Part 1 J/F 32
- Part 2 M/A 50

PRODUCT REVIEW
- Machinery's Handbook, 26th Edition J/A 14
- Precision Brand Tool Black M/A 18

PROJECTS
- Casting Iron in the Home Foundry J/A 22
- Free Pendulum Clock
  - Part 1 J/F 40
  - Part 2 M/A 42
  - Part 3 M/J 46
- Projects Without Drawings J/F 52
- Tapping Machine
  - Part 1 M/A 22
  - Part 2 M/J 28
  - Part 3 J/A 32
- Tesla Turbine
  - Part 1 S/O 18
  - Part 2 N/D 43

Projects Without Drawings J/F 52

R

Replacing Quill Bearings N/D 52

RICE, JOE
- From The Editor J/F 4, M/J 4, J/A 6

S

SCHLUENDER, MARK
- Chips & Sparks
  - Expanding Mandrel M/A 16

Scroll Chucks - Their Care and Repair S/O 58

Selecting Mechanical Fasteners
(see HOFFMAN, EDWARD G.)

Setting Up Fly-cutter Bits S/O 64

SHOP IMPROVEMENTS
- Angle Makes All the Difference N/D 18
- Angle Measurement with an Adjustable Square J/A 61
- Induction Motors and Rotary Phase Converters N/D 26



- How Many Turns? How Many Holes? J/F 56
- Modified Base for a Band Saw, A J/A 64
- Overhauling a Jacobs Chuck N/D 55
- Tapping Machine M/A 22

SLAUSON, MATHEW
- Guest Editorial M/A 4

STIVISON, M. V.
- How Many Turns? How Many Holes? J/F 56

SWINNEY, ROBERT D.
- Angle Measurement with an Adjustable Square J/A 61
- Induction Motors and Rotary Phase Converters N/D 26

T

Tale of Three Smoke-poles N/D 57

Tapping Machine
- Part 1 M/A 22
- Part 2 M/J 28
- Part 3 J/A 32

TECHNIQUE
- Angle Measurement with an Adjustable Square J/A 61

Tesla Turbine
- Part 1 S/O 18
- Part 2 N/D 43

Tilt Body Indexer
- Part 1 M/J 18
- Part 2 J/A 38
- Part 3 S/O 34
- Part 4 N/D 38

THOMPSON, JACK R.
- Clamp Set for Your Mill J/F 61

W

WIEBE, WALTER
- Chips & Sparks
  - Unstuck Chuck, The J/A 69

WILSON, GLENN
- Locating Stop for the Milling Vise, A S/O 62

WIMBERLEY, DAVID
- Chips & Sparks
  - Edge Finders J/A 70

Y

YAMAMOTO, MICHAEL
- Projects Without Drawings J/F 52

YOUNG, RICHARD E.
- Another Edge Finder J/F 50